



TIME SQUARE 10 SHV REPORT

19 June 2026



TIME SQUARE 10 SHV LOCATION



TIME SQUARE 10 SHV LOCATION



TIME SQUARE 10 SHV ANOTHER POINT OF VIEW




TIME SQUARE 10 SHV FLOOR PLAN




SITE PROGRESS UP TO 19 JUNE 2026

BORED PILE FINISHED 192/197p




SONIC TEST PROGRESS UP TO 19 JUNE 2026



SONIC TESTING PROGRESS UP TO 19 JUNE 2026

FINISHED 109/197p



TOOL BOX MEETING



SURVEY INSPECTION



BORED PILE DRILLING



REBAR INSPECTION



DEPTH AND REBAR INSPECTION BEFORE CONCRETE



BENTONITE SLURRY INSPECTION





INSTALL TEMPORATY FENCE



PAVED ACCESS ROAD




PREPARE WORKER CAMPS



MATERIAL CONTROL



CONCRETE STRENGTH TEST



MATERIAL DELIVERED ON SITE




SITE PREPARATION





PASSION FOR PROGRESS!



TIME SQUARE 10 OCEAN VIEW

THE BEST DAY IN OTRES BEACH

THANK YOU!