




TIME SQUARE TK TS335

Weekly Report

Date : 2026.July.09

SITE LOCATION



SITE LOCATION




TIME SQUARE 335 ENVIRONMENT



TOOL BOX MEETING




SITE CLEANING



9F MAIN STRUCTURE PROGRESS


Up to 09th JULY 40% completed



9F External safety netting scaffolding installation

9F MAIN STRUCTURE PROGRESS


Up to 09th JULY 40% completed



Slab 9F Slump Test before Casting Concrete

9F MAIN STRUCTURE PROGRESS

Up to 09th JULY 40% completed



Slab 9F Casting Concrete (Done)

9F MAIN STRUCTURE PROGRESS

Up to 09th JULY 40% completed



Slab 9F Casting Concrete (Done)

9F MAIN STRUCTURE PROGRESS

Up to 09th JULY 40% completed



Slab 9F Casting Concrete (Done)

9F MAIN STRUCTURE PROGRESS

Up to 09th JULY 40% completed



Slab 9F Casting Concrete (Done)

9F MAIN STRUCTURE PROGRESS



Up to 09th JULY 40% completed



Slab 9F Casting Concrete (Done)

9F MAIN STRUCTURE PROGRESS

Up to 09th JULY 40% completed



Slab 9F PT Installation work (Done)

9F MAIN STRUCTURE PROGRESS

Up to 09th JULY 40% completed



Slab 9F PT Installation work (Done)

9F MAIN STRUCTURE PROGRESS

Up to 09th JULY 40% completed



Slab 9F PT Installation work (Done)

9F MAIN STRUCTURE PROGRESS

Up to 09th JULY 40% completed



Slab 8F PT Cutting strand work (Done)

9F MAIN STRUCTURE PROGRESS

Up to 09th JULY 40% completed



Slab 8F PT Grouting work (Done=85%)

9F MAIN STRUCTURE PROGRESS

Up to 09th JULY 40% completed



Slab 9F Slab side formwork removal work (Done)

9F MAIN STRUCTURE PROGRESS

Up to 09th JULY 40% completed



9F Column & Wall rebar installation work (Done=30%)

9F MAIN STRUCTURE PROGRESS

Up to 09th JULY 40% completed



9F Column & Wall rebar installation work (Done=30%)

9F MAIN STRUCTURE PROGRESS

Up to 09th JULY 40% completed



9F Column & Wall rebar installation work (Done=30%)

9F MAIN STRUCTURE PROGRESS


Up to 09th JULY 40% completed



9F Column & Wall rebar installation work (Done=30%)

9F MAIN STRUCTURE PROGRESS


Up to 09th JULY 40% completed



9F Slab rebar installation work (Done)

9F MAIN STRUCTURE PROGRESS


Up to 09th JULY 40% completed



9F Slab rebar installation work (Done)

9F MAIN STRUCTURE PROGRESS

Up to 09th JULY 40% completed



9F Slab rebar installation work (Done)

9F MAIN STRUCTURE PROGRESS



Up to 09th JULY 40% completed



8F Column & Wall Formwork installation work (Done)

9F MAIN STRUCTURE PROGRESS


Up to 09th JULY 40% completed



8F Column & Wall Formwork installation work (Done)

9F MAIN STRUCTURE PROGRESS



Up to 09th JULY 40% completed



8F Slab Formwork installation work (Done)

9F MAIN STRUCTURE PROGRESS



Up to 09th JULY 40% completed



9F Slab Formwork installation work (Done)

9F MAIN STRUCTURE PROGRESS


Up to 09th JULY 40% completed



9F Progress Work



9F MAIN STRUCTURE PROGRESS

Up to 09th JULY 40% completed



9F MEP PROGRESS

Up to 09th JULY 70% completed



9F MEP Slab System Installation work Sleeve & Conduit (Done)

9F MEP PROGRESS

Up to 09th JULY 70% completed



9F MEP Slab System Installation work Sleeve & Conduit (Done)

9F MEP PROGRESS

Up to 09th JULY 70% completed



9F MEP Slab System Installation work Sleeve & Conduit (Done)

9F MEP PROGRESS

Up to 09th JULY 70% completed



9F MEP Slab System Installation work Sleeve & Conduit (Done)

9F MEP PROGRESS


Up to 09th JULY 70% completed



9F MEP Column & Wall System Installation work (Done=30%)

9F MEP PROGRESS


Up to 09th JULY 70% completed



9F MEP Column & Wall System Installation work (Done=30%)

9F MEP PROGRESS

Up to 09th JULY 70% completed



INSPECTION WORK



8F Column & wall Formwork installation Inspection

INSPECTION WORK



8F Column & wall Formwork installation Inspection

INSPECTION WORK



9F Slab Rebar installation Inspection

INSPECTION WORK



9F Slab Rebar installation Inspection

INSPECTION WORK



9F MEP Inspection Sleeve & Conduit installation inspection

INSPECTION WORK



9F MEP Inspection Sleeve & Conduit installation inspection

INSPECTION WORK



8F PT Grouting Inspection

INSPECTION WORK



8F PT Grouting Inspection

INSPECTION WORK




9F PT Installation Inspection

INSPECTION WORK



9F Column & Wall setting out Inspection

INSPECTION WORK




9F Column & Wall setting out Inspection

INSPECTION WORK




9F Column & Wall setting out Inspection

INSPECTION WORK




8F Concrete Compressive Test Inspection

INSPECTION WORK




8F Concrete Compressive Test Inspection

MATERIALS SUPERVISION



MATERIALS SUPERVISION

[illegible][illegible][illegible][illegible][illegible][illegible]



PASSION FOR
PROGRESS

