




# TIME SQUARE

# TK TS335

## Weekly Report

Date : 2026.May.09

# SITE LOCATION



# SITE LOCATION




# TIME SQUARE 335 ENVIRONMENT



# TOOL BOX MEETING




# SITE CLEANING



# 8F STRUCTURE PROGRESS


Up to 09th MAY 30% completed



Inspection Work : Setting out & Column Rebar installation

# 8F STRUCTURE PROGRESS

Up to 09th MAY 30% completed



8F Column Rebar installation

# 8F STRUCTURE PROGRESS




Up to 09th MAY 30% completed



8F Lift wall Formwork installation

# 8F STRUCTURE PROGRESS

Up to 09th MAY 30% completed



8F Beam Rebar installation

# 8F STRUCTURE PROGRESS

Up to 09th MAY 30% completed



8F Beam Rebar installation

# 8F STRUCTURE PROGRESS

Up to 09th MAY 30% completed



8F PT work installation

# 8F STRUCTURE PROGRESS



Up to 09th MAY 30% completed



8F MEP setting out inspection & Sleeve installation

# 8F STRUCTURE PROGRESS


Up to 09th MAY 30% completed



8F Progress Work


# 8F STRUCTURE PROGRESS

Up to 09th MAY 30% completed



# 1F MASONRY PROGRESS

Up to 09th MAY 20% completed




1F Masonry Work : Electric Room Brick Wall Installation



# 1F MASONRY PROGRESS

Up to 09th MAY 20% completed



*PASSION FOR  
PROGRESS*

