


BKK3
SELECTION

Time Square 11 Weekly Report


19. JUNE. 2026

TIME CASTLE

XI



Location Of Site Project





Time Square 11 Point of View






Time Square 11 Point of View





Time Square 11 Point of View



Ground Breaking Ceremony


Time Square 11




CBP Pile progress up to 19.June.2026

0p/168 pile

CBP Progress




■ Done ■ Undone



Main Pile progress up to 19.June.2026


1p/25 pile

Main Pile Progress



■ Done ■ Undone

- Pile casted concrete.
- Pile installed casing.



Coordinate Inspection



Pile PDA-13

Bentonite Inspection: PDA-13



Bentonite inspection before drilling.




Sand content.



Bentonite inspection before casting concrete.



Rebar Inspection



Pile PDA-13

Depth Inspection



Pile PDA-13: 46.45m


Lowering Rebar Cage: PDA-13



Cleaning pile using airlift.



Inserting trimie pipe.



Inserting trimie pipe.

Concrete Casting: PDA-13



Slump Test: 21 cm.



Slump inspection.



Passion For Progress!



Thank You!

TIME SQUARE 11

Boeng Keng Kang 3, Phnom Penh



St. 113

