

Weekly Report

29. OCT. 2026

Project Location



Time Square 11 Point Of View



CBP PROGRESS

CBP PILES (168/168 PILES)



Done
100%



PDA Test Progress

PDA PROGRESS (2/2 Piles)



Done
100%



Time Square 11

Cross-hole Sonic Progress

Up to 29. Oct. 2026 (02/25 Piles)

Sonic Test PROGRESS





Time Square 11

Main Pile Progress

Up to 29. Oct. 2026 (24/25 Piles)

Main Pile PROGRESS



Finished Main Pile Concrete.

Unfinished Main Piles.



Drilling Work







Coordinate Inspection













Bentonite Inspection













Rebar Inspection













Depth Inspection / Lowering Rebar








Pile Cleaning





Slump Inspection









Casting Concrete







Soil Disposal









Passion For Progress!

Thank You!